

Photographing Glover Locomotives

J. Wilder Glover, President of the Glover Machine Works, knew the power of photography when it came to selling Glover steam locomotives. Photographs of the Glover engines were used for post cards, catalog inserts, and advertising materials. From 1902 until the early 1930s, Mr. Glover took photographs of every engine manufactured at the Marietta, Georgia plant. Using a 6.5" x 8.5" large format camera, Wilder took images of the engines during all stages of the assembly process. The most significant picture, however, was taken as each engine was brought out of the assembly shop and prepared for shipment. Many of these photographs contain workers or members of the Glover family.

The Glover Photograph Collection, which is comprised of over 800 glass plate negatives and thousands of photographs, contains images of Glover family gatherings, Glover engines at work in various settings, non-railroad related equipment manufactured at the Glover Machine Works, and photographs of workers and machinery in the interior of the Glover plant.

Restoring the glass plate negatives was made possible by a grant from the Georgia Historical Records Advisory Board, Georgia Department of Archives and History, Office of Secretary of State.

Legend:

LSV = Left Side View

RSV = Right Side View

LSV 3/4 = Left Side 3/4 View

RSV 3/4 = Right Side 3/4 View

LR = Left Rear

RR = Right Rear

LR 3/4 = Left Rear

LF 3/4 = Left Front 3/4 View

RR 3/4 = Right Rear 3/4

RF 3/4 = Right Front 3/4 View

<u>Box</u>	<u>Plate #</u>	<u>RR/Company Name</u>	<u>Date</u>	<u>Builder #</u>	<u>Gauge</u>	<u>Type</u>	<u>View</u>
1	1	Union Cypress #3	1913	14206	Standard	2-6-0	LSV
1	2	1216 Detail					
1	3	Great Eastern Lumber Co. #3	1913	121618	Standard	2-6-0	LF 3/4
1	4	1420 Detail					LR 3/4
1	5	1420 Detail Union Cypress					LF 3/4
1	6	Union Cypress #3	1913	14206	Standard	2-6-0	LSV.
1	7	1420 Detail					
1	8	Westmoreland Lumber #7	1911	12167	Standard	2-6-0	LSV
1	9	Union Cypress R.R. #3	1913	14206	Standard	2-6-0	LR 3/4
1	10	Union Cypress R.R. #3	1913	14206	Standard	2-6-0	LSV
1	11	1420 Detail				2-6-0	LSV
1	12	1420 Detail				2-6-0	RF 3/4
1	13	1420 Detail				2-6-0	LF 3/4

1	14	1420 Detail					2-6-0	LSV
1	15	Lane Bros. #39	1909	11165	Standard		0-4-0	RF 3/4
1	16	Tennessee Coal & Iron #17	1910	7125	36"		0-6-0	RSV
1	17	Tennessee Coal & Iron #17	1910	7125	36"		0-6-0	RSV
1	18	#5 Unidentified Saddle Tank					0-4-0	LSV
1	19	Mutual Mining Co. #2	1911	7126	36"		0-4-0	LSV
1	20	Lane Bros. #39	1909	11165	Standard		0-4-0	RSV
1	21	Lane Bros. #39	1909	11165	Standard		0-4-0	Front
1	22	Lane Bros. #39	1909	11165	Standard		0-4-0	RF 3/4
1	23	Lane Bros. #36					0-4-0	RSV
1	24	Lane Bros. #36					0-4-0	RSV
1	25	Lane Bros. #39	1909	11165	Standard		0-4-0	RSV
1	26	J.T. Wade #1	1911	91414	Standard		0-6-0	LSV
1	27	Cook Jellico #1	1912	81418	36"		0-4-0	LSV
1	28	Cook Jellico #1 with Employee	1912	81418	36"		0-4-0	LF 3/4
1	29	Cook Jellico #1 with Bolan Glover	1912	81418	36"		0-4-0	LSV
1	30	1420 Ten Wheeler Detail					4-6-0	LSV
1	31	1420 Interstate Lumber Co. with ca. 1910 automobile, driver and child, two employees	1908	14202	Standard		4-6-0	LR 3/4
1	32	Graves Brothers #2	1911	16201	Standard		4-6-0	LF 3/4
1	33	1420 Detail 10-W						LSV
1	34	1420 Detail 10-W						RSV
1	35	1420 Detail 10-W						LSV
1	36	Cleveland-Oconee #2	1920	121639	Standard		0-6-0	LSV
1	37	Baum and Van Roy 914	1910	91410			0-4-2	RSV
1	38	Neal Naval Stores #1	1911	10144	Standard		0-4-4	LF 3/4
1	39	R. C. Avent #6					0-6-0	LSV
1	39-B	R. C. Avent and Sons #10	1924	101436	Standard		2-6-0	LF 3/4
1	40	R. C. Avent and Sons #10	1924	101436	Standard		2-6-0	LSV
1	40-B	R. C. Avent #6					0-6-0	LF 3/4
1	41	Cleveland-Oconee #2/Chambers Contracting Co.					0-6-0	LSV
1	42	Hebard Cypress Co. #3	1910	11166	Standard		2-6-0	RF 3/4
1	43	Hebard Cypress Co. #3	1910	11166	Standard		2-6-0	RF 3/4
1	44	Hebard Cypress Co. #3	1910	11166	Standard		2-6-0	RF 3/4
1	45	Hebard Cypress Co. #3	1910	11166	Standard		2-6-0	LSV
1	46	Hebard Cypress Co. #3	1910	11166	Standard		2-6-0	LF 3/4
1	47	Hebard Cypress Co. #3	1910	11166	Standard		2-6-0	LSV
1	48	R.C. Avent #5	1907	11164	Standard		0-6-0	LSV
1	49	Swansboro #2 with Bolan Glover	1907	10141	Standard		2-6-0	RSV
1	50	F. B. Williams #99					0-4-4	LSV
1	51	Kessler & Dehon #2 -914	1910	91410	36"		0-4-2	RSV
1	52	Neal Naval Stores #1	1911	10144	Standard		0-4-4	RSV
1	53	Unidentified 914 with Rear Truck					0-6-4	RSV
1	54	Unidentified 914 with Rear Truck					0-6-4	LSV
1	55	Pittsburgh Lumber Co.					0-4-2	LSV
1	56	R.C. Avent #4	1906	81411	Standard		0-6-4	LF 3/4
1	57	J.B. Blades #1	1907	81416	Standard		0-4-0	LSV
1	58	Little River Lumber Co. #2	1913	101418	36"		0-4-0	FSV
1	59	Mayo Lumber Co. #3	1911	12166	Standard		2-6-0	LSV
1	60	Pawnee L. & L. Co. #103	1914	121621	Standard		2-6-0	LSV

1	61	Suffolk Lumber Co. #1	1911	10145	36"	0-4-4	LSV
1	62	Negative Missing					
1	63	Sloss Sheffield Brookside #1	1913	101417	Standard	0-4-0	LSV
1	64	Suffolk Lumber Co. #1	1911	10145	36	0-4-4	LSV
1	65	Cherokee Brick Co. Red D	1912	121610	Standard	0-6-0	LSV
1	66	J.T. Wade #1	1911	91414	Standard	0-6-0	LSV
1	67	Jacksonville Lumber Co. #1				0-4-2	LSV
1	68	McRainey & Bridges #1	1912	91415	Standard	0-4-0	RSV
1	69	G.F. Butler #10	1910	10165	Standard	0-4-0	LF 3/4
1	70	Jacksonville Lumber Co. #1				0-4-2	LSV
1	71	Kessler Dehon Marion				0-4-0	LSV
1	72	McRainy & Bridges #1	1912	91415	Standard	0-4-0	RSV
1	73	Kessler Dehon Marion #2				0-4-2	LSV
1	74	Kessler Dehon Marion #2				0-4-2	LSV
1	75	1216 Front View Detail					LF 3/4
1	76-A	Powell Lumber Co. Tender #5					LR 3/4
1	76-B	ender Frame - 2 copies					LF 3/4
1	77 - 78	uxbury Repair Job					LF 3/4
1	79	1216 Boiler					LSV
1	80	Walterboro Truck Wheel					LSV
1	81	Boiler for Mexico					RR
1	82	4 Wheel Tender					RSV
1	83	Graves Lumber Co. #1	1911	12165	Standard	2-6-0	LSV
1	84	Tuxbury Repair Job					LF 3/4
1	85	1318 Detail					LF 3/4
1	86	Tuxbury Repair Job					LSV
1	87	10 x 12 Hoisting Engine Reversible					LF 3/4
1	88	Hoisting Engine with Swinging Attachment					RF 3/4
1	89	9 x 10 Hoisting Engine					RF 3/4
1	90	Skidding Engine for Blue Hilton and Dodge Lumber Co.					RSV
1	91 - 92	Hauling in Machine					LSV
1	93	10 x 12 Hoisting Engine					LSV
1	94	5 x 8 Hoisting Engine Detail					Front
1	95 - 96	10 x 12 Skidder Columbus					Front
1	97	Kinder & Northwestern R.R. #101	1910	14203	Standard	4-6-0	RSV
1	98	Kinder & Northwestern R.R. #101	1910	14203	Standard	4-6-0	RSV
1	99	Kinder & Northwestern R.R. #101	1910	14203	Standard	4-6-0	LF 3/4
1	100	W. B. & S. R.R. #100				4-6-0	LSV
1	J-2	Walker Jordan Lumber Co. #1	1924	101437	Standard	2-6-0	LSV
1	J-4	Portland Cement Corporation #1	1924	10169	36"	0-4-0	LSV
1	J-8	Peavy Byrnes Lumber Co.					
2	101	Kinder & Northwestern R.R. #102	1910	14203	Standard	4-6-0	RSV
2	102	Graves Lumber Co. #2	1911	16201	Standard	4-6-0	LSV
2	103	Graves Lumber Co. #2	1911	16201	Standard	4-6-0	RSV
2	104	Kinder & Northwestern R.R. #102	1911	14204	Standard	4-6-0	RSV
2	105	Kinder & Northwestern R.R. #101	1910	14203	Standard	4-6-0	LSV
2	106	Interstate Lumber Co.				4-6-0	LSV
2	107	Interstate Lumber Co.	1908	14202	Standard	4-6-0	LSV
2	108	Interstate Lumber Co.	1908	14202	Standard	4-6-0	LSV

2	109 Florida Tie & Lumber Co. #102	1913	121612	Standard	2-6-0	LSV
2	110 Great Eastern Lumber Co. # 3	1913	121618	Standard	2-6-0	LSV
2	111 Florida Tie & Lumber Co. #102	1913	121612	Standard	2-6-0	LSV
2	112 David O. Anderson #2	1913	121616	Standard	2-6-0	LSV
2	113 Town Creek R.R. & Lumber Co. # 5	1912	12169	Standard	2-6-0	LSV
2	114 Negative Missing					
2	115 C.W. Lacy #21	1912	101415	36"	0-4-0	LSV
2	116 A.J. Twiggs & Son Contractors # 37				0-6-0	LSV
2	117 Powell Lumber Co. # 5	1913	121619	Standard	2-6-0	LSV
2	118 Walterboro Lumber Co. #1				2-6-0	LF 3/4
2	119 Roanoke River Log Co. #3	1913	101419	36"	2-6-0	RSV
2	120 Little River Lumber Co. #2	1913	101418	36"	0-4-0	LSV
2	121 Hammer Lumber Co. #2	1910	10146	36"	0-6-0	LSV
2	122 Middleburg Lumber Co. #1	1913	121617	Standard	0-6-0	LSV
2	123 Baum & Van Roy Crate Co. #2	1911	101410	36"	0-6-0	LSV
2	124 L. Anderson & Co.	1911	10149	Standard	0-6-0	LF 3/4
2	125 Walterboro Lumber Co. #1	1911	10148	Standard	2-6-0	RSV
2	126 Munger & Bennett # 6	1908	10143	Standard	0-6-0	LSV
2	127 S.W. Tyson #1	1913	101416	Standard	0-6-0	RSV
2	128 L. Anderson & Co. #3	1911	10149	Standard	0-6-0	RSV
2	129 B.F. Brinson #2	1912	101413	Standard	0-6-0	LSV
2	130 Negative Missing					
2	131 Chatham Lumber Co. #3		101416	Standard	0-6-0	LSV
2	132 Swansboro Lumber Co. Rebuilt	1907	10141	Standard	2-6-0	RSV
2	133 Baum and Van Roy Crate Co. # 2	1911	101410	36"	0-6-0	LSV
2	134 Chatham Lumber Co. # 3		101416	Standard	0-6-0	LSV
2	135 L. Anderson & Co.	1911	10149	Standard	0-6-0	LSV
2	136 F. B. Williams Cypress Co. #47	1911	10166	Standard	0-6-0	LSV
2	137 10146 Engine and Tender				0-6-0	LSV
2	138 Walterboro Lumber Co. #1	1911	10148	Standard	2-6-0	LSV
2	139 G. F. Butler #10	1910	10165	Standard	0-4-0	LSV
2	140 J.P. Boyle #2	1907	81415	36"	0-4-0	LSV
2	141 Munger & Bennett #6	1908	10143	Standard	0-6-0	LSV
2	142 Westmoreland Lumber Corp.,				2-6-0	LSV
2	142 1014 Engine				2-4-0	LSV
2	142 and J.T. Wade Engine #1				0-6-0	LSV
2	143 Unidentified Engine				4-4-0	LSV
2	143 and Town Creek R.R. & Lumber Co.#5				4-4-0	LSV
2	144 Town Creek R.R. & Lumber Co.#5				0-6-0	LSV
2	144 and J.T. Wade Engine				0-6-0	LSV
2	145 C.W. Lane & Co., Inc. Contractors, Atlanta, GA. and Kinder Northwestern #101					LSV
2	146 Westmoreland Lumber Corp.				2-6-0	LSV
2	146 J. T. Wade Engine				0-6-0	LSV
2	146 and Unidentified Engine and Tender				0-6-0	LSV
2	147 Switch Engine				4-6-0	LSV
2	147 and 2 Unmarked Locomotives					LSV
2	148 Hamilton Ridge Lumber Corp.#1	1913	13181	Standard	2-6-0	LSV
2	149 Powell Lumber Co. #5	1913	121619	Standard	2-6-0	LSV
2	150 Cleveland Oconee Repaired	1920	121639	Standard	0-6-0	LSV

2	151	Great Eastern Lumber Co. #3	1913	121618	Standard	2-6-0	LSV
2	152	A. C. Tuxbury Lumber Co. Repair Job				0-4-0	LSV
2	153	A. C. Tuxbury Lumber Co. Detail					LSV
2	154	A. C. Tuxbury Lumber Co.					LSV
2	155	Forney Elevated Type Locomotive				0-4-4	LSV
2	156	A. C. Tuxbury Lumber Co.				0-6-0	LSV
2	157	A. C. Tuxbury Lumber Co.				0-6-0	LSV
2	158	A. C. Tuxbury Lumber Co. Tender					LSV
2	159	A. C. Tuxbury Lumber Co. Cab				0-6-0	LSV
2	160	A.J. Twiggs & Son Contractors - Manhattan				0-4-4	LSV
2	161	A.J. Twiggs & Son Contractors				0-4-4	LF 3/4
2	162	A.C. Tuxbury Lumber Co. Boiler Construction Photo					LSV
2	163	A.C. Tuxbury Lumber Co. Construction Photo					LSV
2	164	A.C. Tuxbury Lumber Co. Construction Photo					LSV
2	165	Baldwin Locomotive from West Moreland					RSV
2	166	A.C. Tuxbury Lumber Co. Cab Detail					LSV
2	167	E.P. Burton #6 Print	1914	12165	Standard	2-6-0	LSV
2	168	Negative Missing					
2	169	Negative Missing					
2	170	K & NW #101	1910	14203	Standard	4-6-0	RR 3/4
2	171	St. Johns Lumber Co. #1				0-6-0	LSV
2	172	Negative Missing					
2	173	St. Johns Lumber Co. #1				0-6-0	LSV
2	174	St. Johns Lumber Co. #1				0-6-0	LSV
2	175	Union Cypress Co. #3	1913	14206	Standard	2-6-0	LSV
2	176	W. T. Smith's Sons Timber Co. Beverly #4	1914	121624	Standard	2-6-0	LSV
2	177	Pawnee L&L #103 The Little Melvin	1914	121621	Standard	2-6-0	LSV
2	178	J. Davis Reed #1	1914	81420	Standard	0-4-4	LSV
2	179	1318 #1 Detail Left Tank					
2	180	Danville Lumber & Mfg. Co.	1914	121622	Standard	2-6-0	LSV
2	181	Danville Lumber & Mfg. Co.	1914	121622	Standard	2-6-0	LSV
2	182	Union Cypress Co. #3					RF 3/4
2	183	Munger & Bennett #8	1914	101420	36"	2-6-0	LSV
2	184	Roanoke River Log Co. #3	1913	101419	36"	2-6-0	LSV
2	185	B.F. Brinson #2	1912	101413	Standard	0-6-0	LSV
2	186	Little River Lumber Co. #2	1913	101418	36"	0-4-0	LSV
2	187	K & N W R.R. #103 Little Walter Jasper	1913	121620	Standard	2-6-0	LSV
2	188	Rock Creek Lumber Co. #1	1914	13183	Standard	2-6-0	LF 3/4
2	189	J.D. Reed #1	1914	81420	Standard	0-4-4	LSV
2	190	Rock Creek Lumber Co. #1	1914	13183	Standard	2-6-0	LSV
2	191	Rock Creek Lumber Co. Detail	1914	13183	Standard	2-6-0	LSV
2	192	Roanoke River Log Co. Boiler 1014 Detail					LF 3/4
2	193	Roanoke River Log Co. #3					LSV
2	194	Baum & Van Roy Detail					LSV
2	195	Driver Rods					LSV
2	196	Frame Job - Thermit Weld					Front
2	197	1014 Detail					LSV
2	198	914 Vulcan Print					Front
2	199	Small Parts Detail					Front

2	200	Baum & Van Roy Detail						RSV
3	201	Graves Lumber 1216 Detail						LSV
3	202	Graves Lumber 1216 Detail (Tender)						LF 3/4
3	203	Tender Frame						LSV
3	204	Steel Tender Frame						Front
3	205	Graves Lumber Co. #1	1911	12165	Standard	2-6-0		Front
3	206	914 Vulcan Detail						Front
3	207	Steel Tender Frame						Front
3	208	1216 #1 Detail						LSV
3	209	Steel Tender Frame						LSV
3	210	Graves Lumber Co. #1 Front Pilot Detail						LSV
3	211	Steel Tender Frame						LSV
3	212	1216 Graves Lumber 1216 Detail						RF 3/4
3	213	Negative Missing						
3	214	Graves Lumber Co. #1	1911	12165	Standard	2-6-0		RSV
3	215	W.&W. R.R. #5 American Locomotive Mogul				2-6-0		RSV
3	216	Howze Lumber Co. Inc. #5	1911	11168		2-6-0		LSV
3	217	1014 Levert Lumber				0-6-0		LSV
3	218	Graves Lumber Co. #1	1911	12165	Standard	2-6-0		LSV
3	219	Graves Lumber Co. #1	1911	12165	Standard	2-6-0		LSV
3	220	Westmoreland Lumber Corp.	1911	12167	Standard	2-6-0		LSV
3	221	Morgan Lumber Co. #1				2-6-0		LSV
3	222	Town Creek R.R. & Lumber Co. #5	1912	12169	Standard	2-6-0		LSV
3	223	Town Creek R.R. & Lumber Co. #5	1912	12169	Standard	2-6-0		LSV
3	224	Town Creek R.R. & Lumber Co. #5	1912	12169	Standard	2-6-0		LSV
3	225	David O. Anderson #2	1913	121616	Standard	2-6-0		LSV
3	226	Hamilton Ridge Lumber Corporation	1913	13181	Standard	2-6-0		LSV
3	227	Mayo Lumber Co. #3	1911	12166	Standard	2-6-0		LSV
3	228	Clear Creek Lumber Co. #1	1910	12163	Standard	2-6-0		LSV
3	229	Cleveland-Oconee Lumber Co. #2 Repair	1926	121639	Standard	0-6-0		RSV
3	230	Cleveland-Oconee Lumber Co. #2 Repair	1926	121639	Standard	0-6-0		RSV
3	231	Due West Railway #3	1910	12162	Standard	0-6-0		RSV
3	232	Due West Railway #3	1910	12162	Standard	0-6-0		RSV
3	233	Garysburg Manufacturing Co.	1910	12161	36"	2-6-0		LSV
3	234	Morgan Lumber Co.#1 and 2 Saddle Tanks				2-6-0		LSV
3	235	Econfena Lumber Co. #1	1914	13182	Standard	2-6-0		LSV
3	236	1216 Cab #1Detail						LSV
3	237	Rock Creek Lumber Co. #1	1914	13183	Standard	2-6-0		LF 3/4
3	238			13181				Front
3	239	1316 Cab Detail						
3	240	Little River Lumber Co. #2	1913	101418	36"	0-4-0		LSV
3	241	Walterboro Lumber Co. Tender #1						LF 3/4
3	242	1318 Detail						Left
3	243	1216 Detail						RSV
3	244	Walterboro Lumber Co. #1	1913	101418	36"	2-6-0		RR 3/4
3	245	Econfena Lumber Co. #1	1914	13182	Standard	2-6-0		LSV
3	246	4-Wheel Tender Frame						Left
3	247	4-Wheel Rear Truck Frame						LSV
3	248	Amalgamated Phosphate #8	1913	121615	Standard	0-6-0		LSV

3	249	Negative Missing						
3	250	Negative Missing						
3	251	Negative Badly Broken						
3	252	Cherokee Brick S.T.C. #5	1913	121614	Standard	0-6-0	LSV	
3	253	Cherokee Brick Co. Red D #4				0-6-0	LSV	
3	254	Amalgamated #7				0-6-0	LSV	
3	255	Amalgamated #7				0-6-0	RSV	
3	256-258	Negatives Missing						
3	259	Steam Shovel					LSV	
3	260	Negative Missing						
3	261	Sam Jones Detail					RR 3/4	
3	262	Porter Lane Brothers Boiler Assembly					Front	
3	263	Dredge					Shore Side	
3	264	Steel Castings Patterns					Front	
3	265	Log Loader Interstate					Front	
3	266	Log Loader Interstate					Front	
3	267	Mud Washer - Chattahoochee Brick					LR 3/4	
3	268	Georgia Car Co. Inside of Glover Shop					Front	
3	269	Georgia Car Co. Inside of Glover Shop					Front	
3	270	Negative Missing						
3	271	1216 Erecting					RSV	
3	272	Georgia Car Co. Dismantled Inside Glover Shop					Front	
3	273	Powell Lumber Co. #5 Wreck	1913	121619	Standard	2-6-0	RF 3/4	
3	274	Powell Lumber Co. #5 Wreck	1913	121619	Standard	2-6-0	RF 3/4	
3	275)	Brown's Patent Machine					Front	
3	276	Brown's Patent Machine					Front	
3	277	Brown's Patent Machine					Front	
3	278	Brown's Patent Machine					Front	
3	279	Sloss-Sheffield #3 Details, 7x12-4	1906	7124	Standard	0-4-0	RSV	
3	280	Sloss-Sheffield #3 Details, 7x12-4	1906	7124	Standard	0-4-0	Side	
3	281	Sloss -Sheffield #3 Details, 7x12-4	1906	7124	Standard	0-4-0	RSV	
3	282	Sloss- Sheffield #3 Details, 7x12-4	1906	7124	Standard	0-4-0	RSV	
3	283	Sloss-Sheffield #3 Details, 7x12-4	1906	7124	Standard	0-4-0	Front	
3	284	Sloss- Sheffield #3 Details, 7x12-4	1906	7124	Standard	0-4-0	LSV 3/4	
3	285	Sloss- Sheffield #3 Details, 7x12-4	1906	7124	Standard	0-4-0	Front Cab	
3	286	Chattahoochee Brick Co. #44					LSV	
3	287	Negative Missing						
3	288	Negative Missing						
3	288-B	Chattahoochee Brick Co. #44					LSV	
3	289	Upright Marine Engine					LSV	
3	290	Upright Marine Engine					LSV	
3	291	Furnace					RF 3/4	
3	292	Dredge, Shovel End					RF	
3	293	Dredge, Hoisting Engine					LSV	
3	294	Dredge Part					Front	
3	295	Dredge Sternwheel, River View					LSV	
3	296	Dredge, Hoisting Engine					RSV	
3	297- 300	Negatives Missing						

4	301-313	Negatives Missing						
4	314	K & NW #101	1910	14203	Standard	4-6-0	LSV 3/4	
4	315	1420 #101Details					RF 3/4	
4	316	1420 Details					LSV	
4	317	Negative Missing						
4	318A	Gang Saw - Steel Frame						RSV
4	318B	Gang Saw - Steel Frame F.R. Patch Manufacturing Company						LSV
4	318C	Gang Saw - Steel Frame F.R. Patch Manufacturing Company						LSV
4	319A	Wood Gang Saw F.R. Patch Manufacturing Company						LSV
4	319B	Gang Saw - Wood Frame F.R. Patch Manufacturing Company						LSV
4	320	Porter Labeled Glover				0-4-0		RSV
4	321	Jarratt Lumber Co. #7	1915	13185	Standard	2-6-0		LSV
4	322	West Bay Naval Stores	1914	121626	Standard	2-6-0		LSV
4	323	Appomattox Box Shook Co. #2	1917	21632	Standard	2-6-0		LSV
4	324	Appomattox Box Shook Co. #1		101462		2-6-0		LSV
4	325	FL Timber Products Co. #10-Baldwin				2-6-2		RSV
4	326	Appomattox Box Shook Co. #1	1916	101422	Standard	2-6-0		LSV
4	327	Porter Labeled Glover - Photo of Photo				0-4-0		LSV
4	328	Gaffney Lime Co.	1906	9142	Standard	0-4-0		LSV
4	329	Winch-Cotton States						RSV
4	330	Winch-Cotton States						RSV
4	331	Aug. Lindstrom #23883 Mogul Locomotive-Baldwin				2-6-0		RSV
4	332	Side Tank 6 Wheel (Becerra)				0-6-0		RSV
4	333	Baldwin Mogul Locomotive				2-6-0		LSV
4	334	Kessler & Dehon #2				0-6-4		LSV
4	335	Mutual Mining Co. #2	1911	7126	36"	0-4-0		LSV
4	336	Sand Pump						Side
4	337	Central Constancia #14				2-6-0		RSV
4	338	Appomattox Box Shook Co. #1 & #2				2-6-0		LSV
4	339	Appomattox Box Shook Co. Little Harry				2-4-0		LSV
4	340	Appomattox Box Shook Co. Little Harry				2-4-0		LSV
4	341	Appomattox Box Shook Co. #2				2-6-0		LSV
4	342	Appomattox Box Shook Co. #2	1917	21632	Standard	2-6-0		LSV
4	343	Sloss-Sheffield Steel & Iron Co. #26	1915	101423	36"	0-4-0		LF 3/4
4	344	Sloss-Sheffield Steel & Iron Co. #26	1915	101423	36"	0-4-0		LSV
4	345	Sloss-Sheffield Steel & Iron Co. #26	1915	101423	36"	0-4-0		LSV
4	346	Sloss-Sheffield Steel & Iron Co. #27	1915	101425	36"	0-4-0		LSV
4	347	Negative Missing						
4	348	Sloss-Sheffield Steel & Iron Co. #3 Flat Top	1906	7124	Standard	0-4-0		RSV
4	349	Sloss-Sheffield Steel & Iron Co. #28 (pictured with #29)	1916	101426	36"	0-4-0		LSV
4	350	Sloss-Sheffield Steel & Iron Co. #29	1916	101427	36"	0-4-0		LSV
4	351	Sloss-Sheffield Steel & Iron Co. #26 (pictured with #27)	1915	101423	36"	0-4-0		LSV
4	352	Sloss-Sheffield Steel & Iron Co.#28	1916	101426	36"	0-4-0		LSV
4	353	1420 Mogul Detail (Drivers)						LSV
4	354	1420 Mogul Detail						LSV

4	355	1420 Mogul Detail						RSV
4	356	1420 Mogul Detail						LSV
4	357	Southern Timber & Land Co., Inc.					2-6-0	LSV
4	358	Negative Missing						
4	359	W.T. Smith's Sons Timber Co. #4	1914	121624	Standard		2-6-0	LSV
4	360	R. C. Avent #4	1906	81411	Standard		0-6-4	RSV
4	361	Sante Fe #1 Mexico					0-6-0	
4	362	Two Santa Fe Locomotives #1 & #2					0-6-0	LSV
4	363	Negative Missing						
4	364	Santa Fe Locomotives #1 & #2					0-6-0	LSV
4	365	Santa Fe #1 & #2 & Unmarked Mexican Locomotives					0-6-0	LSV
4	366	Tampa Northern and Mr. Thompson					4-6-0	LSV
4	367	Tampa Northern					4-6-0	LSV
4	368	W.T. Cotter Contractor	1905	9141	36"		0-4-0	LSV
4	369	Negative Missing						
4	370	Alabama Construction Company		8148	36"		0-4-0	LSV
4	371	Chattanooga Iron & Coal Co.	1906	81412	36"		0-4-0	LSV
4	372	Swansboro L & L #2	1907	10141	Standard		2-6-0	LSV
4	373	Campbell Coal Mining Co.	1907	81417	36"		0-4-0	LSV
4	374	Hammer Lumber Co. #2	1910	10146	36"		0-6-0	LSV
4	375	F.B.W. Cypress Co. #99					0-4-0	LSV
4	376	L.D. Yancey & Gaffney Lime Co.					0-4-0	LSV
4	377	Waccaman					0-4-2	LSV
4	378	A&C Wright Contractors #2	1905	11161	36"		0-6-0	LSV
4	379	Three Locomotives with Unidentified Lady in Cab						LSV
4	380	Rail Bender						Front
4	381	Steel Derrick						Side
4	382	Cook Jellico Coal Co. #1	1912	81418	36"		0-4-0	LSV
4	383	Excelsior Coal Mining Co.	1904	7121	42"		0-4-0	LSV
4	384	Campbell Coal & Coke Co., Isoline	1903	8144	36"		0-4-0	RSV
4	385	Stratton Brick Co.	1902	8141	36"		0-4-0	RSV
4	386	A.C. Wright, Contractors, Alfred	1905	11161	36"		0-6-0	LSV
4	387	Mexican Locomotive					0-6-0	LSV
4	388	Alabama-Virginia Iron Co. #1, The Douglass	1904	8146	36"		0-4-0	LSV
4	389	Hoisting Engine Crank Shaft in Lathe						Front
4	390	Alabama-Virginia Iron Co. #1, The Douglass	1904	8146	36"		0-4-0	LSV
4	391	Swansboro Land & Lumber Co.	1907	10141	Standard		2-6-0	RSV with child
4	392	Disintegrator Machine						Front
4	393	Disintegrator Machine						LSV
4	394 – 398	Negatives Missing						
4	399	Stratton Brick Company's Yard						RSV
4	400	10x12 Link Motion Hoisting Engine						RSV
5	401	Clark Mill						RSV
5	402	Interstate Lumber Co. #1 with Glover Family and Dog	1908	14202	Standard		4-6-0	RSV
5	403	Rip Saw						Front
5	404	Pug Mill						Front
5	405	Rubbing Bed						RSV

5	406	Steel Derrick						RSV
5	407	Steel Derrick						Front
5	408	Hoisting Engine						Front
5	409	Steel Derrick						Front
5	410	Idler Frame for Gang Saw						Front
5	411- 412	Negatives Missing						
5	413	Shipment for Australia						LSV
5	414	Defective Steel Castings						Front
5	415	Marble Machine						Front
5	416	Rope Sellar						Front
5	417	Roanoke River Log Co. #3	1913	101419	36"	2-6-0		LSV
5	418	J.P. Boyle #2	1907	81415	36"	0-4-0		LSV
5	419	Steel Derrick						Front
5	420	Gang Saw Idler Frame						Front
5	421	Interior View of Glover Machine Works Shop						
5	422	Stratton Brick Co.						RSV
5	423	Negative Missing						
5	424	Roanoke River Log Co.						LSV
5	425	R.C. Avent #5						LSV
5	426	Alabama -Virginia Iron Co., The Douglass				0-4-0		LSV
5	427	7x12x2 Locomotive				0-4-2		LSV
5	428	Terault Land & Lumber Co.				0-4-2		LSV
5	429	Cherokee Brick Co.				0-4-0		RSV
5	430	J.P. Boyle #1	1905	7122	36"	0-4-2		LSV
5	431- 439	Negatives Missing						
5	440	American Passenger 16x24				4-4-0		LSV
5	441	Enville Lumber Co. #10				0-6-0		LSV
5	442	Government Hoist Engine						Front
5	443	Steam Brake Valve						Front
5	444	Joseph Lambert #9	1915	121630	36"	2-6-0		LSV
5	444B	Joseph Lambert #9	1915	121630	36"	2-6-0		LSV
5	445	Rome Brick Co. #2, Florence-Emily	1910	9149	36"	0-4-0		LSV
5	446	Jarratt Lumber Co.	1915	13185	Standard	2-6-0		LSV
5	447	Push Car						LSV
5	448	Four Wheel Switch Engine #233						LSV
5	449	Lindsey Lumber Co. #6						LSV
5	450	1216 Detail						Front
5	451A	Massee & Felton Lumber Co. #3	1920	131814	Standard	2-6-0		LSV
5	451B	Massee & Felton Lumber Co. #3	1920	131814	Standard	2-6-0		LSV
5	452	Brake Valve						Front
5	453	Government Hoisting Engine						RSV
5	454	Government Hoisting Engine						RSV
5	455	Government Hoisting Engine						RSV
5	456	Government Hoisting Engine						RSV
5	457	Steel Skidder						RSV
5	458	Steel Skidder						Upright
5	459	Negative Missing						
5	460	Steel Skidder						Upright
5	461	Hoisting Engine						RSV

5	462	Negative Missing						
5	463	Derrick Iron						RSV
5	464	Steel Skidder						RSV
5	465	Smith Valve Gear						
5	466	Smith Valve Gear						Close Up
5	467	Smith Valve Gear						Front
5	468	J. Davis Reed Locomotive - 2nd Hand - Not Glover Built				4-4-0		RSV
5	469	Seaboard #233				0-4-0		LSV
5	470	Derrick						Front
5	471	Wash Rubber for Rubbing Bed - F.R. Patch Manufacturing						RSV
5	472	Sand Pump						Front
5	473	Derrick Iron - Cut 600						Front
5	474	Derrick Iron						Front
5	475	Derrick Iron - Cut 242						Front
5	476	Derrick Iron - Cut 243						LSV
5	477	Derrick Iron						Various
5	478	Derrick Iron						Various
5	479	Skidder						Upright
5	480	Skidder						Upright
5	481	Skidder						Upright
5	482	Skidder						RF 3/4
5	483	Skidder						RF 3/4
5	484	Skidder						Upright
5	485	Skidder						RSV
5	486	Flue Plates						Front
5	487	Crab						Front
5	488	Crab						Front
5	489	Porter Locomotive				0-4-0		RSV
5	490	Southern Steel Co.				0-4-0		RSV
5	491	Empresa Carenero Carenero #5	1916	121631	36"	0-6-0		LSV
5	492	Empresa Carenero Carenero #5	1916	121631	36"	0-6-0		Front
5	493	Empresa Carenero Carenero #5	1916	121631	36"	0-6-0		LSV
5	494	Empresa Carenero Carenero #5	1916	121631	36"	0-6-0		LSV
5	495	Empresa Carenero Carenero #5	1916	121631	36"	0-6-0		LSV
5	496	Empresa Carenero Carenero #5	1916	121631	36"	0-6-0		LSV
5	497	Empresa Carenero Carenero #5	1916	121631	36"	0-6-0		LSV
5	498	Empresa Carenero Carenero #5	1916	121631	36"	0-6-0		RSV
5	499	Negative Missing						
5	500	Becerra	1916	121631	36"	0-6-0		LSV
6	501	Becerra, Cylinders & Drivers	1916	121631	36"	0-6-0		Front 3/4
6	502	Becerra, Cylinders & Drivers	1916	121631	36"	0-6-0		RRV 3/4
6	503	Becerra, Cab	1916	121631	36"	0-6-0		Interior
6	504	Becerra #5, Brake Rigging	1916	121631	36"	0-6-0		LSV
6	505	Becerra	1916	121631	36"	0-6-0		RSV
6	505_	Becerra	1916	121631	36"	0-6-0		LSV
6	506	Negative Missing						
6	507B	Marble Machinery						Front
6	508	1416 Mogul Detail						LSV

6	509	8 Wheel Side Tank, Porter #66						RSV
6	510	Derrick Bull Wheel						Front
6	511	Old Crawford Engine				0-6-0		LSV
6	512	Negative Missing						
6	513	Fosburgh Lumber Co.#16	1916	14208	Standard	2-6-0		RRV
6	514	Negative Missing						
6	515	Fosburgh Lumber Co.#16	1916	14208	Standard	2-6-0		LSV
6	516	Fosburgh Lumber Co. #16	1916	14208	Standard	2-6-0		LSV
6	517	C. W. Garris #1 Locomotive	1916	101429	Standard	0-4-2		LSV
6	518	C. W. Garris #1 Locomotive	1916	101429	Standard	0-4-2		LSV
6	519	C. W. Garris #1 Locomotive	1916	101429	Standard	0-4-2		LSV
6	520	Negative Missing						
6	521A	Cranford Knight Skidder - 10101						RSV
6	521B	Cranford Knight Skidder - 10101						Upright
6	522	Boiler and Saddle Detail - 1014						RSV
6	523	814-1014 Boiler						RSV
6	524	Kentucky Lumber Co. #5	1916	121627	Standard	2-6-0		LSV
6	525	McKinney & Bennett #8	1916	101430	Standard	0-4-0		LSV
6	526	McKinney & Bennett #8	1916	101430	Standard	0-4-0		LSV
6	527	McKinney & Bennett #8	1916	101430	Standard	0-4-0		LSV
6	528	McKinney & Bennett #8	1916	101430	Standard	0-4-0		LSV
6	529	1013 Boiler						RSV
6	530	1013 Boiler						RR 3/4
6	531	10x10 Skidder Detail						Side
6	532	10x10 Skidder Detail						Front
6	533	10x10 Skidder Detail						Front
6	534	10x10 Skidder Detail						Front
6	535	McKinney & Bennett #8	1916	101430	Standard	0-4-0		LSV
6	536	Cherokee Brick Co. #6	1916	13186	Standard	0-6-0		LSV 3/4
6	537	Cherokee Brick Co. #6	1916	13186	Standard	0-6-0		LSV 3/4
6	538	Cherokee Brick Co. #6	1916	13186	Standard	0-6-0		LSV
6	539	Kentucky Lumber Co.	1916	121627	Standard	2-6-0		LSV
6	540	Coulbourn Bros. #4	1917	81421	36"	2-6-0		LSV
6	541	Negative Missing						
6	542	Coulbourn Bros. #4	1917	81421	36"	2-6-0		LSV
6	543	Kentucky Lumber Co. #4	1916	121627	Standard	2-6-0		LSV
6	544	Anniston Steel Co. #1	1916	101431	30"	0-4-0		LSV
6	545	Coulboourn Bros. #4	1917	81421	36"	2-6-0		LSV
6	546	8 _ x 10 Steel Hoisting Engine-Bradley						LSV
6	547	Zickgraf Lumber Co. #4	1917	101428	Standard	0-6-0		LSV
6	548	Zickgraf Lumber Co. #4	1917	101428	Standard	0-6-0		LSV
6	549	10x10 Steel Skidder						RSV
6	550	10x10 Steel Skidder						Front
6	551	Drum for 10x10 Hoisting Engine						Front
6	552	Drum for 10x10 Hoisting Engine						LSV
6	553	Negative Missing						
6	554	Skidder						Top
6	555	Skidder						Upright
6	556	Skidder						Top

6	557 Skidder							Upright
6	558 Skidder							Upright 3/4
6	559 Skidder							Upright
6	560 Skidder							LSV
6	561 1216 Detail							RR 3/4
6	562 J.F. Prettyman & Sons #4	1917	121629	Standard	2-6-0			LSV
6	563 L.P.T. & W. Ry. #411	1917	13187	Standard	2-6-0			LSV
6	564 L.P.T. & W. Ry. #411	1917	13187	Standard	2-6-0			Front
6	565 L.P.T. & W. Ry. #411	1917	13187	Standard	2-6-0			LSV
6	566 L.P.T. & W. Ry. #411	1917	13187	Standard	2-6-0			LSV
6	567 Norfolk Carolina Timber Corp. #4	1917	101432	36"	2-6-0			LSV 3/4
6	568 Norfolk Carolina Timber Corp. #4	1917	101432	36"	2-6-0			LSV 3/4
6	569 Norfolk Carolina Timber Corp. #4	1917	101432	36"	2-6-0			RR 3/4
6	570 Norfolk Carolina Timber Corp. #4	1917	101432	36"	2-6-0			LSV
6	571 1014 Detail							LSV 3/4
6	572 Norfolk Carolina Timber Corp. #4	1917	101432	36"	2-6-0			LSV
6	573 U.S. Navy Coal Depot	1917	581	24"	0-4-0			LSV
6	574 U.S. Navy Coal Depot #1	1917	582	24"	0-4-0			RF 3/4
6	575 1216 Detail							LSV
6	576 J.F. Prettyman & Sons. #4	1917	121629	Standard	2-6-0			RF 3/4
6	577 Fosburgh Lumber Company #16	1916	14208	Standard	2-6-0			LSV
6	578 Appomattox Box Shook Co. #2	1917	21632	Standard	2-6-0			LSV
6	579 Appomattox Box Shook Co. #2	1917	21632	Standard	2-6-0			RF 3/4
6	580 Detail							LSV 3/4
6	581 Negative Missing							
6	582 J. F. Prettyman & Sons #4	1917	121629	Standard	2-6-0			LSV
6	583 Cylinders 14x20 Bolted Together							LSV
6	584 E. Sondheimer LPT&W #411	1917	13187	Standard	2-6-0			LSV
6	585 E. Sondheimer LPT&W #411	1917	13187	Standard	2-6-0			LSV
6	586 Negative Missing							
6	587 U.S. Naval Coal Depot San Diego, California #1 & #2							LSV
6	588 Negative Missing							
6	589 J.F. Prettyman & Sons #5	1917	14209	Standard	2-6-0			LSV
6	590 J.F. Prettyman & Sons #5	1917	14209	Standard	2-6-0			LSV
6	591 Roper, J.L. Lumber Co. #34	1917	10167	36"	2-4-0			LSV
6	592 Roper, J.L. Lumber Co. #34	1917	10167	36"	2-4-0			LSV
6	593 Roper, J.L. Lumber Co. #34	1917	10167	36"	2-4-0			LSV
6	594 Negative Missing							
6	595 Union Com. de Cuba Hoisting Engine							Upright
6	596 Negative Missing							
6	597 Central Fortuna #4 (J.M. Motley)	1917	101434	30"	0-4-4			LSV
6	598 Central Fortuna #4 (J.M. Motley)	1917	101434	30"	0-4-4			LSV
6	599 Union Com. de Cuba							Upright
6	600 Negative Missing							
7	601 Munger & Bennett #9	1917	101433	Standard	2-6-0			LSV
7	602 Negative Missing							
7	603 Munger & Bennett #9	1917	101433	Standard	2-6-0			LSV
7	604 Munger & Bennett #9	1917	101433	Standard	2-6-0			LSV

7	605	Munger & Bennett #9	1917	101433	Standard	2-6-0	LSV
7	606	Negative Missing					
7	607	HASCO #1	1917	142010	30"	2-6-0	LSV
7	608	Montgomery Lumber Co. (log transfer)					Front
7	609	Negative Missing					
7	610	Carteret Lumber Co. #2	1917	11163	Standard	0-6-0	LSV
7	611	Carteret Lumber Co. #2	1917	11163	Standard	0-6-0	LSV
7	612	Haitian American Sugar Corp. (HASCO) #1	1917	142010	30"	2-6-0	LSV
7	613	Haitian American Sugar Corp.	1917	142010	30"	2-6-0	LSV
7	614	Negative Missing					
7	615	Negative Missing					
7	616	Cleveland-Oconee Lumber Co. #4	1917	121633	Standard	2-6-0	LSV
7	617	Negative Missing					
7	618	S-S.S & I. Co., Brookside #2				0-6-0	LSV
7	619	Cleveland-Oconee Lumber Co. #4	1917	121633	Standard	2-6-0	LSV
7	620	Negative Missing					
7	621	Negative Missing					
7	622	U.S. Navy Yard (Puget Sound) #4	1918	14221	Standard	0-4-0	LSV
7	623	U.S. Navy Yard (Puget Sound) #4	1918	14221	Standard	0-4-0	RF 3/4
7	624	Negative Missing					
7	625	Double Drum Hoisting Engine					
7	626	Central Fortuna #4	1917	101434	30"	0-4-4	LSV
7	627	Negative Missing					
7	628	Santa Cecilia Sugar #1	1918	121634	36"	2-8-00	LSV
7	629	Santa Cecilia Sugar #1	1918	121634	36"	2-8-00	LSV
7	630	U.S. Navy (U.S.N.Y.P.S.) #4	1918	14221	Standard	0-4-0	LSV
7	631	U.S. Navy (U.S.N.Y.P.S.) #4	1918	14221	Standard	0-4-0	LSV
7	632	Single Drum Hoisting Engine					RSV
7	633	Negative Missing					
7	634	U.S. Navy #1				0-4-0	LSV
7	635-638	Negatives Missing					
7	639	Single Drum Hoisting Engine					RSV
7	640	Negative Missing					
7	641	Ferro de Caldas PAEZ #3				2-6-0	LSV
7	642	Negative Missing					
7	643	Ferro de Caldas PAEZ #3				2-6-0	LSV
7	644	HASCO #2					LSV 3/4
7	645	HASCO #2				2-6-0	LSV
7	646	Negative Missing					
7	647	HASCO #2					RSV 3/4
7	648 - 649	N.A.D. St. J. C'K #1 (Naval Ammunition Depot St. Julian's Creek)	1918	142013	Unknown	0-4-0	LSV
7	650	N.A.D. St. J. C'K #1	1918	142013	Unknown	0-4-0	LSV 3/4
7	651	N.A.D. St. J. C'K #1	1918	142013	Unknown	0-4-0	LSV Cab
7	652	N.A.D. St. J. C'K #1	1918	14203	Unknown	0-4-0	LSV Cab
7	653	DuPont Engineering, Old Hickroy #6	1918	81422	36"	0-4-0	LSV
7	654	HASCO #2					LSV Cab
7	655	U.S. Naval Coal Depot #1 San Diego, California	1917	581	24"	0-4-0	LSV
7	656	Negative Missing					
7	657	Empresa Carenero Carenero #5	1916	121631	26"	0-6-0	LSV

7	658	HASCO#2						LSV
7	659	N.A.D. St. J. C'K #1	1918	142013	Unknown	0-4-0		LSV
7	660	N.A.D. St. J. C'K #1	1918	142013	Unknown	0-4-0		RF 3/4
7	661	HASCO #2	1918	15201	30"	2-6-2		RF 3/4
7	662	HASCO #2 Tank						LSV
7	663 – 664	Negatives Missing						
7	665	S.S.S. & Iron Company, Dora #3				0-4-0		LSV
7	666	Negative Missing						
7	667	Savannah River Lumber Co. (Not a Glover)				2-6-0		LSV
7	668	DuPont Engineering Co., Old Hickory #6				0-4-0		LSV
7	669	Santa Cecilia Sugar #1	1918	121634	36"	2-8-00		LSV
7	670	Santa Cecilia Sugar #1	1918	121634	36"	2-8-00		LSV
7	671	Negative Missing						
7	672	DuPont Engineering Co., Old Hickory #6	1918	81422	36"	0-4-0		LSV
7	673	Ferrocarril de Caldas, PAEZ #3				2-6-0		LSV
7	674	Ferrocarril de Caldas, PAEZ #3				2-6-0		LSV
7	675	Negative Missing						
7	676	U.S. N.Y.P.S. #4 (U.S. Navy Yard - Puget Sound)	1918	14221	Standard	0-4-0		LSV
7	677	San Carlos #2	1919	121637	42"	2-6-0		LSV
7	678	San Carlos #2	1919	121637	42"	2-6-0		LSV
7	679	Steel Castings						Front
7	680	Negative Missing						
7	681	Steel Castings						Front
7	682	142011 & 12 Erecting (Frames)						LSV
7	683	142011 & 12 Erecting (Frames)						LSV
7	684	Negative Missing						
7	685	Negative Missing						
7	686	Santa Cecilia Sugar Corp. #1	1918	121634	36"	2-8-00		LSV
7	687	Steel Castings (Spring Cases)						Front
7	688	Santa Cecilia Sugar Corp. #1						LSV 3/4
7	689	HASCO #2	1918	15201	30"	2-6-2		LSV
7	690	B.J. & Co. #1						LSV
7	691	B.J. & Co. #1						LSV
7	692	B.J. & Co. #1						LSV
7	693 – 695	Negatives Missing						
7	696	DuPont Engineering, Old Hickory #7	1918	81423	36"	0-4-0		LSV
7	697	DuPont Engineering, Old Hickory #8	1918	81424	36"	0-4-0		LSV
7	698	Negative Missing						
7	699	B.J. & Company #1 Cab & RR Truck						LSV
7	700 A	B.J. & Company #1						LSV
7	700 B	B.J. & Company #1						LF 3/4
7	700 C	B.J. & Company #1						LSV
8	701	Naval Mine Depot, Yorktown, VA #1	1918	121635	Standard	0-4-0		LSV
8	702	Naval Mine Depot, Yorktown, VA #1	1918	121635	Standard	0-4-0		LSV
8	703	Naval Mine Depot, Yorktown, VA #1	1918	121635	Standard	0-4-0		RF
8	704	Samana & Santiago Ry #3	1919	7127	42"	0-4-2		LSV
8	705 – 706	Negatives Missing						
8	707	Samana & Santiago Ry #3	1919	7127	42"	0-4-2		LSV
8	708	Samana & Santiago Ry #4	1919	13188	42"	2-6-2		LSV

8	709	Samana & Santiago Ry #5	1919	13189	42"	2-6-2	LSV
8	710	Samana & Santiago Ry #3 Detail	1919	7127	42"	0-4-2	RF 3/4
8	711	Marietta Mining Co. (Hoist)					LSV
8	712	Log Transfer					Front
8	713	Skipcar - Marietta Mining Co.					RSV
8	714 – 715	Negatives Missing					
8	716	Cherokee Brick Co. #7	1920	131810	Standard	0-6-0	LSV
8	717	Negative Missing					
8	718	Samana & Santiago Ry #4 Detail	1919	13188	42"	2-6-2	Front
8	719	Samana & Santiago Ry #4 and #5					LSV
8	720	Merrill-Stevens Boiler Section					Front
8	721 – 724	Negatives Missing					
8	725	U.S. Naval Coal Depot, San Diego California #2				0-4-0	LSV
8	726	Negative Missing					
8	727	Samana & Santiago Ry #3					Front
8	728	Log Transfer (Montgomery Lumber Co.)					Front
8	729	Negative Missing					
8	730	Twin Tree Lumber Co. #11	1920	121639	Standard	2-6-0	LSV
8	731 – 732	Negatives Missing					
8	733 A	Cherokee Brick Co. #7 with Shop Crew	1920	131810	Standard	0-6-0	LSV
8	733 B	Cherokee Brick Co. #7	1920	131810	Standard	0-6-0	LSV
8	734 – 735	Negatives Missing					
8	736	A.C. Tuxbury Lumber Co. #8				0-6-0	LSV
8	737	Negative Missing					
8	738 A	Cherokee Brick #8				0-6-0	LSV
8	738 B	Twin Tree Lumber Co. #12	1919	12166	Unknown	2-6-0	LSV
8	739	Negative Missing					
8	740	A.C. Tuxbury Lumber Co.#8	1920	121610	Standard	0-6-0	LSV
8	741 A	A.C. Tuxbury Lumber Co. #9					LSV
8	741 B	A.C. Tuxbury Lumber Co. #9					LSV
8	742 – 743	Negatives Missing					
8	744	Santo Domingo Locomotive 7x12				0-4-2	RF 3/4
8	745	Negative Missing					
8	746	Santo Domingo 13x18 Detail					Front
8	747 – 748	Negatives Missing					
8	749	Santo Domingo Details					RF 3/4
8	750	Negative Missing					
8	751	Santo Domingo Details				2-6-2	LSV
8	752	Negative Missing					
8	753	Santo Domingo Details				2-6-2	LSV
8	754	Santo Domingo #4 and #5				2-6-2	LSV
8	754 – 759	Negatives Missing					
8	755	Santo Domingo #5				2-6-2	LSV
8	756	Santo Domingo Frame					LSV
8	757	Kunhardt #1	1920	131815	42"	0-6-0	Front & LSV 1/4
8	758	Kunhardt #1	1920	131815	42"	0-6-0	RSV
8	760	Kunhardt #1	1920	131815	42"	0-6-0	LSV
8	760	and #2	1920	131816	42"	0-6-0	LSV
8	761	Kunhardt #2	1920	131816	42"	0-6-0	LSV

8	762	Kunhardt #2	1920	131816	42"	0-6-0	LSV
8	763	Negative Missing					
8	764	Kunhardt #2	1920	131816	42"	0-6-0	LSV
8	765	Kunhardt #1	1920	131815	42"	0-6-0	LSV
8	766	Kunhardt #1	1920	131815	42"	0-6-0	LSV
8	767	Kunhardt #2	1920	131816	42"	0-6-0	RSV Tank
8	768	Combined Tiller and Crosshead					RSV
8	769	Milling Machines					Front
8	770	A.T. Small Quarries Co.				0-6-0	LSV
8	771	Milling Machine					Front
8	772	Massee and Felton Lumber Co. #4	1920	131814	Standard	2-6-0	LSV
8	773	Massee and Felton Lumber Co. #4	1920	131814	Standard	2-6-0	LSV
8	774 – 776	Negatives Missing					
8	777	Russian Locomotive Details					Front
8	778	Negative Missing					
8	779	Kunhardt #1	1920	131815	42"	0-6-0	LSV
8	780	Negative Missing					
8	781	Twin Tree Lumber Co. #12	1919	12166	Unknown	2-6-0	LSV
8	782 – 784	Negatives Missing					
8	785	San Domingo #4 Details					Front Cab
8	786	Kommynchet (Russian)	1920	142011	34.8"	2-8-00	LSV
8	787	Santa Cecilia Sugar Corp #2 Details	1919	121638	36"	2-8-00	LSV Cab
8	788	Cherokee Brick Co. #7	1920	131810	Standard	0-6-0	LSV
8	789	Twin Tree Lumber Co. #11	1920	121639	Standard	2-6-0	LSV
8	790	San Domingo #3	1919	7127	42"	0-4-2	LSV
8	791	San Domingo #4	1919	13188	42"	2-6-2	Front
8	792 – 797	Negatives Missing					
8	798	San Domingo Details	1919	13188	42"	2-6-2	LSV Tank
8	799	HASCO #3					LSV
8	800 – 801	Negatives Missing					
	A						
8	801 B	HASCO #3	1918	15202	30"	2-6-2	LSV
8	802	Negative Missing					
8	803	A.C. Tuxbury Lumber Co. #9	1920	131813	Standard	0-6-0	LSV
8	804 – 806	Negatives Missing					
8	807	Steel Tee Pipe					LSV
8	808	Clark Mill (Interior of Mill)					LSV
8	809	Negative Missing					
8	810	Locomotive 5-Wheel Switcher, S-S. S. & I. Co. #10					RSV
8	811	Negative Missing					
8	812	Upright Engine, 7x9					Front
8	813	Pierpont Mfg. Co., Savannah, GA #3	1920	101435	Standard	2-6-0	LSV
8	814	Turret Boring Mill					LSV
8	815 – 816	Negatives Missing					
8	817	Walking Beam					Front
8	818	Zenoria Lumber Co. #5					LSV
8	819	Negative Missing					

8	820	J.F. Prettyman & Sons #7	1920	121640	Standard		2-6-0	LSV
8	821 – 822	Negatives Missing						
8	823	Southern Lumber Co.	1921	131817	Standard		2-6-0	LSV
8	824	Negative Missing						
8	825	Zenoria Lumber Co. #5	1921	13184	Unknown		2-6-0	LSV
8	826	J.F. Prettyman & Sons #7	1920	121640	Standard		2-6-0	LSV
8	827	Negative Missing						
8	828	Ladson Brick and Tile Co. #1	1921	91418		36"	0-4-0	LSV
8	829 – 830	Negatives Missing						
8	831	Retorts - Swift and Company						LSV
8	832 – 833	Negatives Missing						
8	834	Dredge Parts						LSV
8	835	Dredge Parts						Front
8	836	Dredge Parts						Front
8	837- 845	Negatives Missing						
8	846	Dump Car						Front
8	847 – 850	Negatives Missing						
8	851	Pulverizer						LSV
8	852	Pulverizer						LSV
8	853 – 855	Negatives Missing						
8	856	Saw Mill Castings						Front
8	857 – 858	Negatives Missing						
8	859	Haitian American Sugar Corp. #4				30"	2-6-2	LF 3/4
8	860	McNeil Coal Co. #1	1922	101438		36"	0-4-0	LSV
8	861	Negative Missing						
8	862	Fox Bros. Company, Eusebia #1						LSV
8	863	Negative Missing						
8	864	Haitian American Sugar Corp, #4				30"	2-6-2	RR 3/4
8	865	Haitian American Sugar Corp. #4				30"	2-6-2	LSV
8	866 – 867	Negatives Missing						
8	868	Cliffside R.R. Co. #181923		131818	Standard		2-6-2	LSV
8	869	Cliffside R.R. Co. #18	1923	131818	Standard		2-6-2	LSV
8	870	Porter Locomotive					0-4-4	RSV
8	871 A	Cliffside R.R. Co. #18	1923	131818	Standard		2-6-2	LF & Side
8	872	Anderson Lumber Co. #4	1923	121641	Standard		2-6-0	LSV
8	873	Anderson Lumber Co. #4	1923	121641	Standard		2-6-0	LSV
8	874	Negative Missing						
8	875	Anderson Lumber Co. #4	1923	121641	Standard		2-6-0	LSV
8	876	White Lake Lumber Co. #6	1923	121642	Standard		2-6-0	LSV
8	877	Baldwin Locomotive #814						LSV
8	878	Stover Lumber Co. #5						LSV
8	879 – 880	Negatives Missing						
8	881	McNeil Coal Co. #1					0-4-0	LSV
8	882	Negative Missing						
8	883	White Lake Lumber Co. #6	1923	121642	Standard		2-6-2	LSV
8	884 – 885	Negatives Missing						
8	886 A	Edgar Bros. Co. #10	1923	101439		36"	0-4-0	LSV
8	887 – 901	Negatives Missing						
8	902	Annealing Car with R.R. Castings						

- 8 903 – 906 Negatives Missing
- 8 907 Driving Boxes on Cincinnati Planer
- 8 908 – 917 Negatives Missing
- 8 918 Castings in Foundry
- 8 919 – 930 Negatives Missing
- 8 931 New Addition to Buildings (Foundry)
- 8 Un-numbered Pipe Fittings, Y-Base and Single-Sweep Tees